APPARATUS AND METHODS FOR FORMING TORODIAL WINDINGS FOR CURRENT SENSORS

ABSTRACT

[0029] In accordance with one embodiment of the present invention, a method of forming a toroidal winding assembly comprises: forming a longitudinal assembly having a first assembly end and a second assembly end; bending the longitudinal assembly to form a generally toroidal assembly; and bonding the first assembly end to the second assembly end to form the toroidal winding assembly.